


SN. 09/869, 299



ENCLOSURE A



AT THE LOCATIONS BETWEEN THE SUPPORTS, HEIGHT DIFFERENCES MAY OCCUR DUE TO DIFFERENT SAGGING WHEN USING PANELS WHICH DO NOT OVERLAP OR WHICH SHOW ONLY A SINGLE OVERLAPPING (in a tongue and groove there is a double overlapping). AS A RESULT, VISUALLY DISTURBING UNEVENNESSES ARE CREATED WHICH MAY RESULT IN GAPS AND PANELS MAY BECOME TWISTED.